May 23, 2023

Mr. Matthew Griffin Facilities Supervisor Kyrene School District No. 28 8700 South Kyrene Road Tempe, AZ 85284-2197

Subject: 6-Month Surveillance Inspection

Asbestos-Containing Building Materials Kyrene de La Estrella Elementary School

2620 East Liberty Lane, Phoenix

Dear Mr. Griffin:

FM GROUP INC has completed the 6-Month Surveillance Inspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

Items of significance are: None.

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

FM GROUP INC

Michael Hall

Environmental Division Manager

Zach Ridgeway

AHERA Building Inspector

Attachments: 6-Month Surveillance Inspection Forms

6-Month Surveillance Inspection Tables



6-MONTH SURVEILLANCE INSPECTION ASBESTOS-CONTAINING BUILDING MATERIALS

School/Facility: Kyrene de la Estrella Elementary School	Inspection Date: 04/07/2023
Building: <u>Main Building</u>	

Inspector: Zach Ridgeway Cert. No.: 4380-15665-030823 Signature:

Material Description	Material Code	Material Observed		Material Condition Status		Material Condition Description	Assessment Classification	
				Same	Changed	(If Change Noted)		
Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap, White	M·BUR·01	Y	N	x			1 2 3 4 5 6 7*	
Mastic (Penetrations And Flashings), Black, Tar-Like	M·MAS·02	Y	N	x			1 2 3 4 5 6 7*	
Sealant (Flashings), Gray, Pliable	M·SLT·03	Υ	N	Х			1 2 3 4 5 6 7*	
Fire Door Insulation, Metal/Wood Cladding	M·FDI·34	Y	N	Х			1 2 3 4 5 6 7*	
Adhesive (FRP), Brown, Brittle	M·ADH·51	Υ	N	Х			1 2 3 4 5 6 7*	
Stucco, Gray, Cementitious	S·STU·56	Υ	N	Х			1 2 3 4 5 6 7*	
Brick, 4"X6", Red, Cementitious	M·BRK·59	Υ	N	Х			1 2 3 4 5 6 7*	
Mortar, Gray, Cementitious	M·MRT·60	Y	N	Х			1 2 3 4 5 6 7*	
Mastic, Yellow, Tacky	M·MAS·62	Υ	N	х			1 2 3 4 5 6 7*	
Vinyl Composition Tile (Strip), 2"X24", Red, Smooth	M·VCT·64	Y	N	Х			1 2 3 4 5 6 7*	
Vinyl Composition Tile (Strip), 2"X24", Black, Smooth	M·VCT·65	Y	N	Х			1 2 3 4 5 6 7*	
Vinyl Composition Tile (Strip), 2"X24", Green, Smooth	M·VCT·66	Y	N	Х			1 2 3 4 5 6 7*	
Vinyl Composition Tile (Strip), 2"X24", Blue, Smooth	M·VCT·67	Y	N	Х			1 2 3 4 5 6 7*	

*Assessment Classifications

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

6-MONTH SURVEILLANCE INSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
M·BUR·01	М	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap, White	Roof	Assumed	NF	G	81,000	SF
M·MAS·02	М	Mastic (Penetrations And Flashings), Black, Tar-Like	Roof	Assumed	NF	G	2,000	SF
M·SLT·03	М	Sealant (Flashings), Gray, Pliable	Roof	Assumed	NF	G	50	SF
M EDI 04	M	Fire Door Insulation, Metal/Wood	Describe	Assumed	NF	G	2.500	SF
M·FDI·34	IVI	Cladding	Reception	Assumed	NF.	G	3,528	SF
			Treatment					
			Treatment B					
			Hall 01					
			Workroom 01					
			Faculty Lounge					
			Janitor 01					
			Janitor 01A					
			Men's Restroom					
			Women's Restroom					
			Assistant Principal					
			Conference 17					
			Kindergarten 01					
			Storage 02					
			Kindergarten 02					
			Kindergarten 03					
			Storage 03					
			Classroom 04					
			Classroom 05					
			Classroom 06					
			Classroom 07					

MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
		Boy's Restroom 01					
		Girl's Restroom 01					
		Water/Heater 01					
		Math Supply					
		Classroom 17					
		Classroom 18					
		Classroom 19					
		Classroom 20					
		Classroom 21					
		Boy's Restroom 3					
		Girl's Restroom 3					
		Water/Heater 03					
		Music 23					
		Music 24					
		Music Storage 01					
		Music Storage 02					
		Electrical 03					
		Ramada					
							+
							+
							1
 		*					
	TYPE	TYPE DESCRIPTION	TYPE	TYPE	TYPE	TYPE	TYPE

MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
		Electrical 01					
		Yard Area 1					
		Kitchen					
		Living Room					
		Yard Area 2					
		Gifted 29					
		Art 30					
		Art Storage 01					
		Art Yard 01					
		Room 31					
		Classroom 32					
		Classroom 33					
		Classroom 34					
		Classroom 35					
		Classroom 36					
		Classroom 37					
		Boy's Restroom 2					
	TYPE	TYPE DESCRIPTION	TYPE DESCRIPTION LOCATION M/S/T Kitchen Service Yard Y02 Water/Heater 04 Electrical Yard Multi-Purpose Storage Mechanical Room 01 Boy's Restroom 4 Girl's Restroom 4 Electrical 01 Yard Area 1 Kitchen Living Room Yard Area 2 Gifted 29 Art 30 Art Storage 01 Art Yard 01 Room 31 Classroom 32 Classroom 34 Classroom 35 Classroom 36	M/S/T	TYPE	TYPE	TYPE

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			Classroom 43					
			Classroom 44					
			Preschool 45					
			Media Center 46					
			A/V Workroom					
			Computer Classroom 47					
			Office 48					
			Room 49					
			Unisex Restroom					
			Special Ed 50					
			Special Ed 51					
			Special Ed 52					
			Speech 53					
			Extended Resource 54					
			Corridor 01					
			Room Co 01A					
			Corridor 02					
			Corridor 03					
			Room Co 03A					
			Room Co 03B					
			Corridor 04					
			Corridor 05					
			Room Co 05A					
			Room Co 05B					
			Corridor 06					
			Corridor 07					
			Room Co 07A					
			Corridor 08					
			Corridor 09					
			Corridor 10					
			Room Co 10A					
			Room Co 10B					
			Corridor 11					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			Room Co 11A					
			Room Co 11B					
			Corridor 12					
			Corridor 13					
			Room Co 13A					
M·ADH·51	M	Adhesive (FRP), Brown, Brittle	Water/Heater 03	Assumed	NF	G	150	SF
			Kitchen					
			Room 31					
S·STU·56	S	Stucco, Gray, Cementitious	Service Yard Y02	Assumed	NF	G	25	SF
M·BRK·59	М	Brick, 4"X6", Red, Cementitious	Exterior	Assumed	NF	G	40	SF
M·MRT·60	М	Mortar, Gray, Cementitious	Exterior	Assumed	NF	G	4	SF
M·MAS·62	M	Mastic, Yellow, Tacky	Kitchen	Assumed	NF	G	300	SF
			Living Room					
			Restroom 01					
			Restroom 02					
M·VCT·64	М	Vinyl Composition Tile (Strip), 2"X24", Red, Smooth	Multi-Purpose	Assumed	NF	G	50	SF
M·VCT·65	М	Vinyl Composition Tile (Strip), 2"X24", Black, Smooth	Multi-Purpose	Assumed	NF	G	50	SF
M·VCT·66	M	Vinyl Composition Tile (Strip), 2"X24", Green, Smooth	Multi-Purpose	Assumed	NF	G	50	SF
M·VCT·67	M	Vinyl Composition Tile (Strip), 2"X24", Blue, Smooth	Multi-Purpose	Assumed	NF	G	50	SF

Certifies that

Zachary Ridgettat

has attended and received instruction in the EPA approved course

AHERA Building Inspector Initial

March 6-8 2023

and successfully completed and passed the competency exam

Certificate: 4380-15665-030823

Date of Examination: 08-Mar-2023

Date of Expiration: 08-Mar-2024 THE ASBESTOS INSTITUTE

Director

602-864-6564 - www.theasbestosinstitute.com

Approved Institutor

20033 N. 19th Ave, Building 6, Phoenix, AZ 85027

This training meets off requirements for asbestos certification under Taxic Substance Control Act 1718, 11.