

May 23, 2023

Mr. Matthew Griffin
Facilities Supervisor
Kyrene School District No. 28
8700 South Kyrene Road
Tempe, AZ 85284-2197

**Subject: 6-Month Surveillance Inspection
Asbestos-Containing Building Materials
Kyrene de la Colina Elementary School
13612 South 36th Street, Phoenix**

Dear Mr. Griffin:

FM GROUP INC has completed the 6-Month Surveillance Inspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

Items of significance are: None.

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

FM GROUP INC



Michael Hall
Environmental Division Manager



Zach Ridgeway
AHERA Building Inspector

*Attachments: 6-Month Surveillance Inspection Forms
6-Month Surveillance Inspection Tables*




6-MONTH SURVEILLANCE INSPECTION ASBESTOS-CONTAINING BUILDING MATERIALS

School/Facility: Kyrene de la Colina Elementary School

Inspection Date: 04/07/2023

Building: Main

Inspector: Zach Ridgeway Cert. No.: 4380-15665-030823

Signature: 

Material Description	Material Code	Material Observed		Material Condition Status		Material Condition Description (If Change Noted)	Assessment Classification
				Same	Changed		
Mortar (Glass Block), Gray, Cementitious	M-MRT-05	Y	N	x			1 2 3 4 5 6 7*
Adhesive (TWP), Brown, Brittle	M-ADH-07	Y	N	x			1 2 3 4 5 6 7*
Fire Door Insulation, Metal Cladding	M-FDI-13	Y	N	x			1 2 3 4 5 6 7*
Fire Door Insulation, Wood Cladding	M-FDI-14	Y	N	x			1 2 3 4 5 6 7*
Pipe End Sealant, White, Brittle	M-PES-18	Y	N	x			1 2 3 4 5 6 7*
Sink Acoustical Coating, Gray, Rough	M-SAC-20	Y	N	x			1 2 3 4 5 6 7*
Ceramic Mosaic Tile, Various Sizes, Red, Smooth, Orange/Blue/Brown/Tan/Yellow/Cream (Pattern)	M-CMT-30	Y	N	x			1 2 3 4 5 6 7*
Grout, Gray, Cementitious	M-GRT-37	Y	N	x			1 2 3 4 5 6 7*
Brick, 3"X16", Red, Cementitious	M-BRK-40	Y	N	x			1 2 3 4 5 6 7*
Mortar, Gray, Cementitious	M-MRT-41	Y	N	x			1 2 3 4 5 6 7*
Adhesive (FRP), Brown, Brittle	M-ADH-45	Y	N	x			1 2 3 4 5 6 7*
Glazed Wall Tile, 4"X6", Brown, Smooth	M-GWT-46	Y	N	x			1 2 3 4 5 6 7*
Grout, Gray, Cementitious	M-GRT-47	Y	N	x			1 2 3 4 5 6 7*
Ceramic Mosaic Tile, 2"X2", Tan, Smooth, Peppered	M-CMT-48	Y	N	x			1 2 3 4 5 6 7*
Grout, Gray, Cementitious	M-GRT-49	Y	N	x			1 2 3 4 5 6 7*
Stair Tread, 12"X72", Vinyl-Like, Circle Pattern	M-VST-52	Y	N	x			1 2 3 4 5 6 7*
Mastic, Yellow, Tacky	M-MAS-53	Y	N	x			1 2 3 4 5 6 7*
Adhesive (GWT), Yellow, Brittle	M-ADH-63	Y	N	x			1 2 3 4 5 6 7*
Expansion Joint, Brown, Fibrous	M-EXJ-66	Y	N	x			1 2 3 4 5 6 7*
Gasket, 8", Gray, Paper-Like	M-GAS-67	Y	N	x			1 2 3 4 5 6 7*
Mastic (Penetrations And Flashings), Black, Tar-Like	*M-MAS-69	Y	N	x			1 2 3 4 5 6 7*
Paint (Penetrations And Flashings), Silver, Brittle, White, Pliable	*M-PNT-73	Y	N	x			1 2 3 4 5 6 7*
Built-Up Roofing, Black, Asphaltic, Gray Gravel Cap	*M-BUR-74	Y	N	x			1 2 3 4 5 6 7*
Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Brown Mineral Cap	*M-APR-75	Y	N	x			1 2 3 4 5 6 7*
Concrete, Gray, Cementitious	M-CON-76	Y	N	x			1 2 3 4 5 6 7*
Fire Door Insulation, Metal/Wood Cladding	M-FDI-124	Y	N	x			1 2 3 4 5 6 7*



6-MONTH SURVEILLANCE INSPECTION ASBESTOS-CONTAINING BUILDING MATERIALS

***Assessment Classifications**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.



**6-MONTH SURVEILLANCE INSPECTION
ASBESTOS-CONTAINING BUILDING MATERIALS**

School/Facility: Kyrene de la Colina Elementary School

Inspection Date: 04/07/2023

Building: Storage Building

Inspector: Zach Ridgeway Cert. No.: 4380-15665-030823

Signature: 

Material Description	Material Code	Material Observed		Material Condition Status		Material Condition Description (If Change Noted)	Assessment Classification
				Same	Changed		
Asphalt Prepared Roofing (Shingles), Black, Asphaltic, Brown Mineral Cap	M-APR-01	Y	N	x			1 2 3 4 5 6 7*
Vapor Barrier Felt, Black, Asphaltic	M-VBF-02	Y	N	x			1 2 3 4 5 6 7*

***Assessment Classifications**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

6-MONTH SURVEILLANCE INSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
M-MRT-05	M	Mortar (Glass Block), Gray, Cementitious	Reception	Assumed	NF	G	150	SF
			Treatment					
			Nurse Office					
			Faculty Lounge					
			Speech					
			Computer Room 33					
			Special Ed. Room 35					
			Special Ed. Room 36					
			Special Ed. Room 37					
			Kinder Room 10					
			Kinder Room 11					
			1st Grade Room 12					
			1st Grade Room 13					
			2nd Grade Room 14					
			1st Grade Room 15					
			2nd Grade Room 16					
			2nd Grade Room 17					
			3rd Grade Room 18					
			3rd Grade Room 19					
			3rd Grade Room 20					
			Gifted Room 21					
			4th Grade Room 22					
			4th Grade Room 23					
			4th Grade Room 25					
			5th Grade Room 26					
			5th Grade Room 27					
			6th Grade Room 28					
			6th Grade Room 29					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			6th Grade Room 30					
			Art Room 31					
			Multi-Purpose					
			Corridor 1					
			Corridor 2					
			Corridor 3					
			North Foyer					
			Corridor 5					
			Corridor 7					
			Corridor 8					
			Corridor 9					
			Foyer South					
			Corridor 12					
			Corridor 14					
			Exterior					
M-ADH-07	M	Adhesive (TWP), Brown, Brittle	Reception	Assumed	NF	G	2,750	SF
			School Office					
			Principal					
			Faculty Lounge					
			Speech					
			Library					
			Computer Room 33					
			Special Ed. Room 35					
			Special Ed. Office					
			Special Ed. Room 36					
			Special Ed. Room 37					
			Kinder Room 10					
			Kinder Room 11					
			1st Grade Room 12					
			1st Grade Room 13					
			2nd Grade Room 14					
			1st Grade Room 15					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			2nd Grade Room 16					
			2nd Grade Room 17					
			3rd Grade Room 18					
			3rd Grade Room 19					
			3rd Grade Room 20					
			Gifted Room 21					
			4th Grade Room 22					
			4th Grade Room 23					
			4th Grade Room 25					
			5th Grade Room 26					
			5th Grade Room 27					
			6th Grade Room 28					
			6th Grade Room 29					
			6th Grade Room 30					
			Art Room 31					
			Music					
M-FDI-13	M	Fire Door Insulation, Metal Cladding	Reception	Assumed	NF	G	819	SF
			Treatment					
			Faculty Lounge					
			West Girl's Foyer					
			West Boy's Restroom					
			Music					
			Multi-Purpose					
			Kitchen					
			Kinder Room 11					
			Kinder Room 10					
			North Boy's Restroom					
			North Girl's Foyer					
			Art Room 31					
			Corridor 12					
			Corridor 10					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			Corridor 7					
			Corridor 6					
			Corridor 5					
			Corridor 3					
			Corridor 1					
			Corridor 2					
			Exterior					
M-FDI-14	M	Fire Door Insulation, Wood Cladding	Reception	Assumed	NF	G	1,344	SF
			Storage 1					
			East Foyer					
			Faculty Lounge					
			Hall 1					
			Hall 2					
			Staff Men's Restroom					
			Staff Women's Restroom					
			Storage 2					
			Speech					
			Library Workroom					
			Computer Room 33					
			A/V					
			Janitor					
			Special Ed. Room 35					
			Special Ed. Room 36					
			Special Ed. Room 37					
			West Boy's Restroom					
			West Girl's Foyer					
			West Girl's Restroom					
			Hall 4					
			Kinder Room 10					
			Kinder Room 11					
			1st Grade Room 12					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			1st Grade Room 13					
			2nd Grade Room 14					
			1st Grade Room 15					
			2nd Grade Room 16					
			2nd Grade Room 17					
			3rd Grade Room 19					
			North Boy's Restroom					
			Hall 3					
			North Girl's Foyer					
			North Girl's Restroom					
			3rd Grade Room 18					
			3rd Grade Room 20					
			Gifted Room 21					
			4th Grade Room 22					
			4th Grade Room 23					
			5th Grade Room 24					
			4th Grade Room 25					
			5th Grade Room 26					
			5th Grade Room 27					
			6th Grade Room 28					
			6th Grade Room 29					
			6th Grade Room 30					
			Art Room 31					
			Music					
			Music Storage					
			Multi-Purpose					
			Multi-Purpose Storage					
			West Water/Heater Closet					
			P.E. Storage					
			Kitchen					
			South Boy's Restroom					
			South Girl's Restroom					
			Corridor					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			Corridor 1					
			Corridor 2					
			Corridor 3					
			Corridor 4					
			North Foyer					
			Corridor 5					
			Corridor 6					
			Corridor 7					
			Corridor 8					
			Corridor 9					
			Foyer South					
			Corridor 10					
			Corridor 11					
			Corridor 12					
			Corridor 14					
M-PES-18	M	Pipe End Sealant, White, Brittle	Reception	Assumed	NF	G	200	SF
			School Office					
			Treatment					
			Nurse Office					
			Nurse Restroom					
			Hearing					
			Storage 1					
			East Foyer					
			Principal					
			Principal's Closet					
			Assistant Principal					
			Work Room					
			Faculty Lounge					
			Phone Room					
			Hall 1					
			Hall 2					
			Staff Men's Restroom					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			Staff Women's Restroom					
			Storage 2					
			Speech					
			Library					
			Library Workroom					
			Computer Room 33					
			A/V					
			Janitor					
			Electrical					
			Special Ed. Room 35					
			Special Ed. Office					
			Special Ed. Room 36					
			Special Ed. Room 37					
			Timeout					
			West Boy's Restroom					
			West Girl's Foyer					
			West Girl's Restroom					
			Hall 4					
			Kinder Room 10					
			Kinder Room 10 Toilet					
			Kinder Room 11					
			Kinder Room 11 Toilet					
			1 st Grade Room 12					
			1 st Grade Room 13					
			2 nd Grade Room 14					
			1 st Grade Room 15					
			North Boy's Restroom					
			North Girl's Foyer					
			North Girl's Restroom					
			Hall 3					
			North Water Heater Closet					
			2 nd Grade Room 16					
			2 nd Grade Room 17					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			3 rd Grade Room 18					
			3 rd Grade Room 19					
			3 rd Grade Room 20					
			Gifted Room 21					
			4 th Grade Room 22					
			4 th Grade Room 23					
			5 th Grade Room 24					
			4 th Grade Room 25					
			5 th Grade Room 26					
			5 th Grade Room 27					
			6 th Grade Room 28					
			6 th Grade Room 29					
			6 th Grade Room 30					
			Art Room 31					
			Music					
			Music Storage					
			Stage					
			East Wing					
			West Wing					
			Multi-Purpose					
			Multi-Purpose Storage					
			West Water Heater Closet					
			P.E. Storage					
			P.E. Office					
			Kitchen					
			South Boy's Restroom					
			South Girl's Restroom					
			Corridor					
			Corridor 1					
			Corridor 2					
			Corridor 3					
			Corridor 4					
			North Foyer					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			Corridor 5					
			Corridor 6					
			Corridor 7					
			Corridor 8					
			Corridor 9					
			Foyer South					
			Corridor 10					
			Corridor 11					
			Corridor 12					
			Corridor 14					
M-SAC-20	M	Sink Acoustical Coating, Gray, Rough	East Foyer	Assumed	NF	G	275	SF
			Faculty Lounge					
			Speech					
			Library Workroom					
			Computer Room 33					
			Special Ed. Room 35					
			Special Ed. Room 36					
			Special Ed. Room 37					
			Music					
			Kinder Room 10					
			Kinder Room 11					
			1st Grade Room 12					
			1st Grade Room 13					
			2nd Grade Room 14					
			1st Grade Room 15					
			2nd Grade Room 16					
			2nd Grade Room 17					
			3rd Grade Room 18					
			3rd Grade Room 19					
			3rd Grade Room 20					
			Gifted Room 21					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			4th Grade Room 22					
			4th Grade Room 23					
			5th Grade Room 24					
			4th Grade Room 25					
			5th Grade Room 26					
			5th Grade Room 27					
			6th Grade Room 28					
			6th Grade Room 29					
			6th Grade Room 30					
			Art Room 31					
M-CMT-30	M	Ceramic Mosaic Tile, Various Sizes, Red, Smooth, Orange/Blue/Brown/Tan/Yellow/ Cream (Pattern)	Faculty Lounge	Assumed	NF	G	5	SF
M-GRT-37	M	Grout, Gray, Cementitious	Faculty Lounge	Assumed	NF	G	4	SF
M-BRK-40	M	Brick, 3"X16", Red, Cementitious	Library	Assumed	NF	G	40,000	SF
			East Wing					
			Multi-Purpose					
			Multi-Purpose Storage					
			P.E. Storage					
			P.E. Office					
			Corridor					
			Corridor 4					
			Corridor 7					
			Corridor 8					
			Corridor 11					
			Equipment Pit					
			East Courtyard					
			South Courtyard					
			Exterior					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
M-MRT-41	M	Mortar, Gray, Cementitious	Library	Assumed	NF	G	4,000	SF
			East Wing					
			Multi-Purpose					
			Multi-Purpose Storage					
			P.E. Storage					
			P.E. Office					
			Corridor					
			Corridor 4					
			Corridor 7					
			Corridor 8					
			Corridor 11					
			Equipment Pit					
			East Courtyard					
			South Courtyard					
			Exterior					
M-ADH-45	M	Adhesive (FRP), Brown, Brittle	Janitor	Assumed	NF	G	20	SF
M-GWT-46	M	Glazed Wall Tile, 4"X6", Brown, Smooth	West Boy's Restroom	Assumed	NF	G	5,000	SF
			West Girl's Foyer					
			West Girl's Restroom					
			North Boy's Restroom					
			North Girl's Foyer					
			North Girl's Restroom					
			South Boy's Restroom					
			South Girl's Restroom					
M-GRT-47	M	Grout, Gray, Cementitious	West Boy's Restroom	Assumed	NF	G	500	SF
			West Girl's Foyer					
			West Girl's Restroom					
			North Boy's Restroom					
			North Girl's Foyer					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			North Girl's Restroom					
			South Boy's Restroom					
			South Girl's Restroom					
M-CMT-48	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth, Peppered	West Boy's Restroom	Assumed	NF	G	2,500	SF
			West Girl's Foyer					
			West Girl's Restroom					
			North Boy's Restroom					
			North Girl's Foyer					
			North Girl's Restroom					
			South Boy's Restroom					
			South Girl's Restroom					
M-GRT-49	M	Grout, Gray, Cementitious	West Boy's Restroom	Assumed	NF	G	250	SF
			West Girl's Foyer					
			West Girl's Restroom					
			North Boy's Restroom					
			North Girl's Foyer					
			North Girl's Restroom					
			South Boy's Restroom					
			South Girl's Restroom					
M-VST-52	M	Stair Tread, 12"X72", Vinyl-Like, Circle Pattern	East Wing	Assumed	NF	G	50	SF
			West Wing					
M-MAS-53	M	Mastic, Yellow, Tacky	East Wing	Assumed	NF	G	50	SF
			West Wing					
M-ADH-63	M	Adhesive (Gwt), Yellow, Brittle	West Boy's Restroom	Assumed	NF	G	5,000	SF
			West Girl's Foyer					
			West Girl's Restroom					
			North Boy's Restroom					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			North Girl's Foyer					
			North Girl's Restroom					
			South Boy's Restroom					
			South Girl's Restroom					
M-EXJ-66	M	Expansion Joint, Brown, Fibrous	Exterior	Assumed	NF	G	1,250	SF
M-GAS-67	M	Gasket, 8", Gray, Paper-Like	Equipment Pit	Assumed	NF	G	30	SF
M-MAS-69	M	Mastic (Penetrations And Flashings), Black, Tar-Like	Main Roof <i>Sampled 2/15/2021</i>	Assumed	NF	G	1,000	SF
M-PNT-73	M	Paint (Penetrations And Flashings), Silver, Brittle, White, Pliable	Main Roof <i>Sampled 2/15/2021</i>	Assumed	NF	G	1,000	SF
M-BUR-74	M	Built-Up Roofing, Black, Asphaltic, Gray Gravel Cap	Main Roof <i>Sampled 2/15/2021</i>	Assumed	NF	G	57,000	SF
M-APR-75	M	Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Brown Mineral Cap	Main Roof <i>Sampled 2/15/2021</i>	Assumed	NF	G	1,500	SF
M-CON-76	M	Concrete, Gray, Cementitious	Exterior	Assumed	NF	G	25,000	SF
M-FDI-124	M	Fire Door Insulation, Metal/Wood Cladding	A1 Girl's Restroom	Assumed	NF	G	630	SF
			A1 Boy's Restroom					
			Room A1 38					
			Room A1 39					
			Room A1 40					
			Room A1 41					
			Room A1 42					
			Room A1 43					
			Room A1 44					
			Room A1 45					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			Room A1 46					
			A1 Corridor 16					
			A1 Corridor 17					
			Room A2 47					
			Room A2 48					
			Room A2 49					
			Room A2 50					
			A2 Corridor 14					
			A2 Corridor 15					
			Exterior					

6-MONTH SURVEILLANCE INSPECTION TABLE
IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
M-APR-01	M	Asphalt Prepared Roofing (Shingles), Black, Asphaltic, Brown Mineral Cap	Roof	Assumed	NF	G	120	SF
M-VBF-02	M	Vapor Barrier Felt, Black, Asphaltic	Roof	Assumed	NF	G	120	SF

THE ASBESTOS INSTITUTE

Certifies that

Zachary Ridgeway

has attended and received instruction in the EPA approved course

AHERA Building Inspector Initial

on

March 6-8 2023


and successfully completed and passed the competency exam.

Certificate:
4380-15665-030823

Date of Examination:
08-Mar-2023

Date of Expiration:
08-Mar-2024


William T. Cavness
Director


Approved Instructor

THE ASBESTOS INSTITUTE

20033 N. 19th Ave, Building 6, Phoenix, AZ 85027
602-864-6564 – www.theasbestosinstitute.com

This training meets all requirements for asbestos certification under Basic Substance Control Act Title II.