May 23, 2023

Mr. Matthew Griffin Facilities Supervisor Kyrene School District No. 28 8700 South Kyrene Road Tempe, AZ 85284-2197

Subject: 6-Month Surveillance Inspection

Asbestos-Containing Building Materials Kyrene de las Manitas Elementary School 1201 West Courtney Lane, Phoenix

Dear Mr. Griffin:

FM GROUP INC has completed the 6-Month Surveillance Inspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

Items of significance are: None

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

FM GROUP INC

Michael Hall

Environmental Division Manager

Zach Ridgeway

AHERA Building Inspector

Attachments: 6-Month Surveillance Inspection Forms

6-Month Surveillance Inspection Tables



6-MONTH SURVEILLANCE INSPECTION ASBESTOS-CONTAINING BUILDING MATERIALS

School/Facility: Kyrene de las Manitas Elementary School	Inspection Date: 04/07/2023
Building: Main Building	

Inspector: Zach Ridgeway Cert. No.: 4380-15665-030823 Signature:

Material Description			terial erved		aterial ion Status	Material Condition Description	Assessment Classification
				Same	Changed	(If Change Noted)	
Fire Door Insulation, Metal/Wood Cladding	M·FDI·22	Y	N	Х			1 2 3 4 5 6 7*
Glazed Wall Tile, 4"X4", Tan, Smooth	M·GWT·41	Y	N	Х			1 2 3 4 5 6 7*
Grout, Gray, Cementitious	M·GRT·42	Υ	N	Х			1 2 3 4 5 6 7*
Ceramic Mosaic Tile, 2"X2", Gray, Smooth, Tan Pattern	M·CMT·43	Y	N	х			1 2 3 4 5 6 7*
Grout, Gray, Cementitious	M·GRT·44	Υ	N	х			1 2 3 4 5 6 7*
Adhesive (FRP), Brown, Brittle	M·ADH·47	Υ	N	Х			1 2 3 4 5 6 7*
Glazed Wall Tile (Pattern), 4"X4", Gray, Smooth	M·GWT·48	Y	N	х			1 2 3 4 5 6 7*
Glazed Wall Tile (Pattern), 4"X4", Black, Smooth	M·GWT·49	Y	N	Х			1 2 3 4 5 6 7*
Vinyl Composition Tile (Strip), 2x24", Black, Smooth	M·VCT·60	Y	N	Х			1 2 3 4 5 6 7*
Vinyl Composition Tile (Strip), 2x24", Red, Smooth	M·VCT·61	Y	N	х			1 2 3 4 5 6 7*
Vinyl Composition Tile (Strip), 2x24", Green, Smooth	M·VCT·62	Y	N	Х			1 2 3 4 5 6 7*
Vinyl Composition Tile (Strip), 2x24", Yellow, Smooth	M·VCT·63	Y	N	Х			1 2 3 4 5 6 7*
Vinyl Composition Tile (Strip), 2x24", Blue, Smooth	M·VCT·64	Y	N	Х			1 2 3 4 5 6 7*

*Assessment Classifications

- Damaged or significantly damaged thermal system insulation ACBM. 1.
- 2. Damaged friable surfacing ACBM.
- Significantly damaged friable surfacing ACBM. 3.
- Damaged or significantly damaged friable miscellaneous ACBM. 4.
- ACBM with potential for damage. 5.
- 6.
- ACBM with potential for significant damage.
 Any remaining friable ACBM or friable suspected ACBM. 7.

6-MONTH SURVEILLANCE INSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
M·FDI·22	М	Fire Door Insulation, Metal/Wood Cladding	Reception	Assumed	NF	G	3,570	SF
		-	Electrical 02					
			Supply					
			Women's Restroom					
			Men's Restroom					
			Literacy Center					
			Lounge					
			Phone					
			Office 01					
			Office 01 Closet					
			Work Room					
			Treatment					
			Classroom 101					
			Classroom 102					
			Storage 05					
			Classroom A-1					
			Classroom A-2					
			Co 13a					
			Classroom A-3					
			Classroom A-4					
			Classroom A-5					
			Classroom A-6					
			Classroom B-1					
			Classroom B-2					
			Classroom B-3					
			Classroom B-4					
			Classroom B-5					
			Co 10b					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			Classroom B-6					
			Boy's Restroom 1					
			Girl's Restroom 1					
			Janitor 01					
			Laundry					
			Gifted Resource					
			Co 10a					
			Art					
			Art Yard					
			Multi-Purpose					
			Table Storage					
			Electrical 01					
			Girl's Restroom 2					
			Boy's Restroom 2					
			Day Storage 101					
			Kitchen					
			W/H					
			Service Yard					
			Day Storage 102					
			P.E. Storage					
			Stage					
			North Wing					
			South Wing					
			Music 101					
			Music 102					
			Girl's Restroom 3					
			Boy's Restroom 3					
			Girl's Restroom 4					
			Boy's Restroom 4					
			Janitor 03					
			Classroom C-1					
			Co 04b					
			Classroom C-2					
			Oldooroom 0-2					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			Classroom C-3					
			Classroom C-4					
			Classroom C-5					
			Classroom C-6					
			Classroom C-7					
			Classroom C-8					
			Classroom D-1					
			Classroom D-2					
			Classroom D-3					
			Classroom D-4					
			Classroom D-5					
			Co 04a					
			Classroom D-6					
			Boy's Restroom 5					
			Girl's Restroom 5					
			Janitor 02					
			Storage 01					
			Library					
			Room L-1					
			A/V Workroom					
			A/V Storage					
			Extended Resource					
			Special Programs					
			Speech					
			Special Programs 2					
	†		Special Programs 3					
	†		Itinerant Office					
			Building Manager					
			Classroom E-1					+
			Classroom E-2					
			Co 01a					
			Classroom E-3					1
			Classroom E-4					+

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			Classroom E-5					
			Classroom E-6					
			Kindergarten K-101					
			Storage 03					
			Kindergarten K-102					
			Kindergarten K-103					
			Storage 02					
			Mechanical Room					
			Mechanical Yard					
			Corridor 01					
			Corridor 02					
			Corridor 03					
			Corridor 04					
			Corridor 05					
			Corridor 06					
			Corridor 07					
			Corridor 08					
			Corridor 09					
			Corridor 10					
			Corridor 11					
			Corridor 12					
			Corridor 13					
			Corridor 14					
			Living Room					
			Apt Yard					
			Exterior					
M·GWT·41	M	Glazed Wall Tile, 4"X4", Tan, Smooth	Women's Restroom	Assumed	NF	G	9,000	SF
		C5011	Men's Restroom		1			
			Nurse Restroom					
			101 Restroom					+
			102 Restroom					+

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			Unisex Restroom 1					
			Unisex Restroom 2					
			Girl's Restroom 2					
			Boy's Restroom 2					
			Girl's Restroom 3					
			Boy's Restroom 3					
			Girl's Restroom 4					
			Boy's Restroom 4					
			Boy's Restroom 5					
			Girl's Restroom 5					
			K-101 Restroom					
			K-102 Restroom					
			K-103 Restroom					
M·GRT·42	M	Grout, Gray, Cementitious	Women's Restroom	Assumed	NF	G	100	SF
		. , ,	Men's Restroom					
			Nurse Restroom					
			101 Restroom					
			102 Restroom					
			Unisex Restroom 1					
			Unisex Restroom 2					
			Girl's Restroom 2					
			Boy's Restroom 2					
			Girl's Restroom 3					
			Boy's Restroom 3					
			Girl's Restroom 4					
			Boy's Restroom 4					
			Boy's Restroom 5					
			Girl's Restroom 5					
			K-101 Restroom					
			K-102 Restroom					
			K-103 Restroom			_		1

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
M·CMT·43	М	Ceramic Mosaic Tile, 2"X2", Gray, Smooth, Tan Pattern	Women's Restroom	Assumed	NF	G	5,000	SF
		,	Men's Restroom					
			Nurse Restroom					
			Boy's Restroom 1					
			Girl's Restroom 1					
			Girl's Restroom 3					
			Boy's Restroom 3					
			Girl's Restroom 4					
			Boy's Restroom 4					
			Boy's Restroom 5					
			Girl's Restroom 5					
			K-101 Restroom					
			K-102 Restroom					
			K-103 Restroom					
M·GRT·44	M	Grout, Gray, Cementitious	Women's Restroom	Assumed	NF	G	500	SF
	1.4.	Croat, Cray, Comonutado	Men's Restroom	Accumou		-		- 0.
			Nurse Restroom					
			Boy's Restroom 1					
			Girl's Restroom 1					
			Girl's Restroom 3					
			Boy's Restroom 3					
			Girl's Restroom 4					
			Boy's Restroom 4					
			Boy's Restroom 5					
			Girl's Restroom 5					
			K-101 Restroom					
			K-102 Restroom					
			K-103 Restroom					
M·ADH·47	М	Adhesive (FRP), Brown, Brittle	Kitchen	Assumed	NF	G	150	SF
			Janitor 03					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
M·GWT·48	M	Glazed Wall Tile (Pattern), 4"X4", Gray, Smooth	Women's Restroom	Assumed	NF	G	500	SF
		Gray, Grissin	Men's Restroom					
			Nurse Restroom					
			101 Restroom					
			102 Restroom					
			Unisex Restroom 1					
			Unisex Restroom 2					
			Girl's Restroom 2					
			Boy's Restroom 2					
			Girl's Restroom 3					
			Boy's Restroom 3					
			Girl's Restroom 4					
			Boy's Restroom 4					
			Boy's Restroom 5					
			Girl's Restroom 5					
			K-101 Restroom					
			K-102 Restroom					
			K-103 Restroom					
M·GWT·49	М	Glazed Wall Tile (Pattern), 4"X4",	Women's Restroom	Assumed	NF	G	500	SF
W 1 49	IVI	Black, Smooth	Women's Restroom	Assumed	INF	G	500	SF
		,	Men's Restroom					
			Nurse Restroom					
			101 Restroom					
			102 Restroom					
			Unisex Restroom 1					
			Unisex Restroom 2					
			Girl's Restroom 2					
			Boy's Restroom 2					
			Girl's Restroom 3					
			Boy's Restroom 3					
			Girl's Restroom 4					

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA
			Boy's Restroom 4					
			Boy's Restroom 5					
			Girl's Restroom 5					
			K-101 Restroom					
			K-102 Restroom					
			K-103 Restroom					

^{*}The following materials were missing from the Multi-Purpose room: M·VCT·60, M·VCT·61, M·VCT·62. M·VCT·63 and M·VCT·64.

Certifies that

Zachary Ridgettay

has attended and received instruction in the EPA approved courns

AHERA Building Inspector Initial

On

March 6-8 2023

and successfully completed and passed the competency exam.

Certificate: 4380-15665-030823

Date of Examination: 08-Mar-2023

Date of Expiration: 08-Mar-2024

Approved Intersector

Director

THE ASBESTOS INSTITUTE

20033 N. 19th Ave, Building 6, Phoenix, AZ 85027

602-864-6564 - www.theasbestosinstitute.com

This training recots all requirements for ashestos certification under Toxic Substance Control Act 7114. 11.